



Assembly Instructions. **In-line XY-Stand, Product No. OP-006 333**




Items included in delivery kit:

ITEM	QTY.	PART NO.
1	1	Linear guide assembly
2	1	Boom Assembly
3	8	MC6S M6x22 A2
4	4	Slot nut_M6
5	6	Washer 6x17x1mm
6	2	OP-006 460_C, L-bracket
7	1	Cable holder, short
8	2	UNC0,25-20 x0,7, Black
9	2	Cable tie
10	1	Cable holder



Mount the In-line stand according to the below picture. Adjust height of the stand for 240 mm working distance (Distance between PCB and front edge of HD camera).



If OP-006 334, 4-directions Camera Tilt unit



is ordered:

Working distance (Distance between PCB and front edge of HD camera) must be **190-192mm** in order to achieve focus in all tilt directions.

