

Monitoring Report

Reference of the board : auto

Serial Number : PROD001


Inspected by : Thomas

Date : mercredi 27 février 2013

Number of components inspected : 236 / 236

Number of defects : 10

Number of production order: PROD001



Location	Defect	Pic deft	Pic ref	Repair defect
R5 B200096 Comment : Sans	Damaged Comp			<input type="checkbox"/>
R2 B200120 Comment : Sans	MANATHAN			<input type="checkbox"/>
R24 B200120 Comment : Sans	Bad Value			<input type="checkbox"/>
R73 B200120 Comment : Sans	Bad Value			<input type="checkbox"/>
C17 G020048 Comment : Sans	Missing Comp			<input type="checkbox"/>
C27 G020048 Comment : Sans	Bad Value			<input type="checkbox"/>

Monitoring Report

Reference of the board :auto

Serial Number :PROD001


Inspected by :Thomas









Date :mercredi 27 février 2013

Number of components inspected :236 / 236

Number of defects :10

Number of production order:PROD001



Location	Defect	Pic deft	Pic ref	Repair defect
C74 G100036 Comment : Sans	Polarity defect			<input type="checkbox"/>
C221 G120037 Comment : Sans	Polarity defect			<input type="checkbox"/>
D9 I600004 Comment : Sans	Polarity defect			<input type="checkbox"/>
U34 N630008 Comment : Sans	Damaged Comp			<input type="checkbox"/>